




GISON Pneumatic Tools

GP-869 Air Screw Driver



PARTS LIST

★ :Consuming Part

Item No.	Part No.	Description	Qty.	Item No.	Part No.	Description	Qty.
1	86901	Retaining Ring	1	24	86924	Cylinder	1
2	86902	Washer	2	25	86925	Pin (ø 2x18)	1
3	86903	Bushing	1	26	86926	Rear Plate	1
4	86904	Spring	1	27	86927	Ball Bearing (626)	1
7	86907	Front Cap	1	28	86928	Handle	1
8	86908	O-Ring (P37.82x1.78)	1	29	86929	Switch Lever	1
9	86909	Bushing	1	30	86930	Air Inlet (18)	1
10	86910	Washer	1	31	86931	Air Inlet (19)	1
11	86911	Ring	1	32	86932	Hook	1
12	86912	Anvil	1	33	86933	Pin (ø 3x26)	1
13	86913	Steel Ball (ø 1/8")	1	34	86934	Pin (ø 2x6)	1
14	86914	Pin (ø 4.5x29)	2	35	86935	O-Ring (P8x1.5)	1
15	86915	Hammer	2	36	86936	O-Ring (P11x2.4)	2
16	86916	Hammer Case	1	37	86937	Bushing	1
17	86917	Hammer Cam	1	38	86938	Valve Rod	1
18	86918	Washer	1	39	86939	O-Ring (P3x1.9)	1
19	86919	Bolt	1	40	86940	Spring	1
20	86920	Ball Bearing (R6)	1	41	86941	O-Ring (P5x1.9)	1
21	86921	Front Plate	1	42	86942	Reverse Valve	1
22	86922	Rotor	1	43	86943	Pin (ø 2x20)	1
23	86923	Rotor Blade	6				