




GISON Pneumatic Tools

GP-802 Air Screw Driver



PARTS LIST

✳ :Consuming Part

Item No.	Part No.	Description	Qty.	Item No.	Part No.	Description	Qty.
1	80201	Retaining Ring	1	28	80228	Ball Bearing (6001)	1
2	80202	Washer	2	29	80229	Ball Bearing (608)	1
3	80203	Bushing	1	30	80230	Front Plate	1
4	80204	Spring	1	31	80231	Rotor	1
6	80206	Stopping Wheel (ø 10mm)	1	32	80232	Rotor Blade	5
7	80207	Front Cap	1	33	80233	Cylinder	1
8	80208	Bushing	1	34	80234	Pin (ø 2x14)	1
9	80209	Anvil	1	35	80235	Rear Plate	1
10	80210	Steel Ball (ø 1/8")	1	36	80236	Ball Bearing (696)	1
11	80211	Spring	1	37	80237	Muffler	1
12	80212	Retaining Ring	1	38	80238	O-Ring (P34x2)	1
13	80213	Steel Ball (ø 2.5mm)	15	39	80239	Handle	1
14	80214	Clutch	1	40	80240	Switch Lever	1
15	80215	Steel Ball (ø 4mm)	4	41	80241	Air Inlet (18)	1
16	80216	Driving Rod	1	42	80242	Air Inlet (19)	1
17	80217	Washer	1	43	80243	Hook	1
18	80218	Spring	1	44	80244	Pin (ø 2x18)	1
19	80219	Washer	1	46	80246	O-Ring (P8x1.9)	3
21	80221	Bolt	1	47	80247	Bushing	1
22	80222	Washer	1	48	80248	O-Ring (P3x1.9)	1
23	80223	Ball Bearing (6001)	1	49	80249	Valve Rod	1
24	80224	Gear Ring	1	50	80250	Spring	1
25	80225	Gear Seat	1	51	80251	O-Ring (P5x1.9)	1
26	80226	Gear	2	52	80252	Reverse Valve	1
27	80227	Pin (ø 4x13)	2	53	80253	Pin (ø 2x20)	1